












<p>E1</p>  <p>8x30mm x16</p>	<p>T1</p>  <p>x8</p>	<p>N1</p>  <p>L=35mm x8</p>	<p>M1</p>  <p>12x15mm x8</p>	<p>S5</p>  <p>4x25mm x6</p>	<p>K1</p>  <p>x2</p>
---	--	---	--	---	--




1	x	2
2	x	4
3	x	2
4	x	1

E1  8x30mm X8	M1  12x15mm X8	K1  GLUE
--	--	--




Diagrams showing correct glue application (smiley face, checkmark) and incorrect application (sad face, X).




1 x2
3 x2

Circular inset showing M1 washer and E1 cylinder being inserted into the assembly.




Warning diagrams showing correct (smiley face, checkmark) and incorrect (sad face, X) placement of the M1 washer and E1 cylinder.

N1  L=35mm X8
--






2

Circular inset showing N1 screw being inserted into the assembly.



Warning diagram showing correct (smiley face, checkmark) and incorrect (sad face, X) placement of the N1 screw.

T1  X8	K1  GLUE
--	--



1 x4
2 x2
3





Diagram showing glue application to the T-shaped part.



Warning diagrams showing correct (smiley face, checkmark) and incorrect (sad face, X) placement of the T-shaped parts.

x2

S5



4x25mm

X6

