


MEDIA







OFFICE

LIVING

MAJA
MÖBEL

U112











11.07.2022




1

maja-moebel.de



U112




U112




E709322
(350 x 350 x 50)












31.063
2x



32.063
2x



33.226
2x







<p>E701000</p>  <p>12x</p>	<p>E701153</p>  <p>14x Ø 15 mm</p>	<p>E701231</p>  <p>18x</p>	<p>E701149</p>  <p>4x Ø 12 mm</p>
<p>E701010</p>  <p>8x</p>	<p>E704052</p>  <p>4x</p>	<p>E700570</p>  <p>4x M4 x 9 mm</p>	<p>E700000</p>  <p>16x Ø 4,0 x 15 mm</p>
<p>E703017</p>  <p>4x</p>			

U112




Probleme bei der Montage?
Problems with assembly?


<https://www.maja-moebel.de/de/news/montagetipps>





1




2







4




5





6




7







10




11



12




13




14


2x



15



E700570
M4x9mm



20.481

20.480

