


Ax1 	Bx1 	Cx1 	Dx1 	C1x1
D2x1 	Ex1 	Fx1 	Gx1 	G2x2
Hx1 	Ix1 	Jx1 	Kx1 	Lx1
Mx1 	N1x1 	N2x1 	Ox1 L: $\frac{965}{38.0}$	Px1 L: $\frac{985}{38.8}$
Qx1 	Rx2 	Sx2 	Tx2 	Ux4
Vx20 	Wx20 	Xx20 M6x $\frac{25}{1.0}$	Yx8 M6x $\frac{35}{1.4}$	Zx7 M6x $\frac{55}{2.2}$
ZAx10 	ZBx10 M8x $\frac{35}{1.4}$	ZCx18 M8x $\frac{40}{1.6}$	ZDx30 M8	ZEx3 M6
ZFx49 $\Phi 8x \frac{22}{0.9}$	ZGx34 $\Phi 6x \frac{18}{0.7}$	ZHx2 	ZIx8 M8x $\frac{60}{2.4}$	ZJx1
ZKx2 			 mm inch x2	



7

ZFx2
Xx4

8

ZFx6
Xx6

9

ZGx6
Xx6

10

ZDx8
ZFx16
ZCx8

11

ZIx4
ZDx10
ZFx16
ZCx2

12

ZDx4
ZFx4
ZCx4

13

ZDx2 ZFx2
ZCx2

ZB
ZFx2
ZH

ZBx2
ZDx2
ZFx6
ZCx2

14

Sx2
ZCx2
ZDx2

ZIx4
ZFx7
ZDx4

ZIx4
ZDx6
ZFx7
ZCx2

15

Wx20 ZAx10 Vx20

16

ZJ
ZK

17