










YS-201



Order	(L*W) MM
①	800*370=1
②	800*370=1
③	470*60=1
④	470*78=1
⑤	470*300=1
⑥	470*279=1
⑦	470*295=1
⑧	500*100=1
⑨	500*100=1
⑩	568*249=1
⑪	568*249=1



A

V








C

F

G

H—H

I



∅15*13mm
=34

∅8*40mm
=34

∅8*40mm
=20

∅20*0.3mm=34

25*65*25
=4

67*67*40mm
=2

4*14mm
=40






J

K

L

P

Q



∅20*8mm
=2



∅10*43mm
=2

∅6*70mm
=2


∅18*4mm
=4

∅15*20mm
=4


1





3





C=12*
V=22*




2



A=4*
V=4*
C=4*




4



A=11*




5



A=11*






7




A=8*

V=8*


C=4*




6




H-H=2*




I=16*




8




Q=4*





9




I=12*
G=2*




11





10





I=12*
G=2*





12




13





14




F=34




15




16




17




19



18



20



OK!