




ASSEMBLY INSTRUCTION

Hardware


A	B	C	D	E	1	2	3	4	5	6	
 ø6*ø16*1.5	 M6*10	 M6*20	 M6*30	 4MM							
X8	X12	X2	X2	X1	X1	X1	X1	X1	X1	X1	

Assemble Step


①




②



③



④



All screws are assembled 100%
on a flat surface