





Model 3100 - 90x160 cm
 Model 3101 - 90x180 cm
 Model 3102 - 100x200 cm





- | | | | |
|-------------|--|-------------|--|
| (D) | Montageanleitung
3100/3101/3102 | (GB) | Assembly instructions
3100/3101/3102 |
| (FR) | Notice de montage
3100/3101/3102 | (IT) | Istruzioni di montaggio
3100/3101/3102 |
| (NL) | Handleiding voor de montage
3100/3101/3102 | (PL) | Instrukcja montażu
3100/3101/3102 |
| (CZ) | Montážní návod
3100/3101/3102 | (SK) | Návod na montáž
3100/3101/3102 |
| (HU) | Szerelési útmutató
3100/3101/3102 | (RO) | Instrucțiuni de montaj
3100/3101/3102 |
| (TR) | Montaj talimatı
3100/3101/3102 | (RU) | Инструкция по монтажу
3100/3101/3102 |




Name • Nom • Nome • Naam • Nazwa • Jméno •
Názov • Név • Denumire • Isim • Название

Nr. • No. • N° • Номер • Č • Sz




Typ • Type • Tip • Tipus • Tipo • Tun





0
10
20
30
40
50
60
70
80
90
100
110
120
130
140
150
160
170
180
190
200





Ab Ø10x40mm 12x	Ac Ø10x70mm 8x	De Ø4x55mm 4x	Eb Ø7x60mm 12x	Ga Ø6.3x11mm 40x	Ha 20x16mm Ø6.5mm 20x	Ld 4mm 1x	Lg 12x	M Ø26x3mm 8x
-------------------------------	------------------------------	-----------------------------	------------------------------	--------------------------------	--	-------------------------	----------------------	----------------------------




3




4



5



6



7

