



# Assembly Instruction










SKU:WF321418











# Parts List




# Parts List

<p>①</p>  <p>X4</p>	<p>②</p>  <p>X2</p>
<p>③</p>  <p>X4</p>	<p>④</p>  <p>X6</p>
<p>⑤</p>  <p>X8</p>	<p>⑥</p>  <p>X4</p>
<p>⑦</p>  <p>X2</p>	<p>⑧</p>  <p>X1</p>
<p>⑨</p>  <p>X2</p>	

# Hardware

<p>Ⓐ</p>  <p>M8×70mm</p> <p>X8</p>	<p>Ⓑ</p>  <p>M8×45mm</p> <p>X10</p>	<p>Ⓒ</p>  <p>M8×15mm</p> <p>X4</p>	<p>Ⓓ</p>  <p>M6×20mm</p> <p>X12</p>
<p>Ⓔ</p>  <p>M4</p> <p>X1</p>	<p>Ⓕ</p>  <p>M5</p> <p>X1</p>	<p>Ⓖ</p>  <p>M6×70mm</p> <p>X4</p>	<p>Ⓗ</p>  <p>X6</p>


1



**x2**

	ⓐ x4
	ⓔ x1
	ⓐ x4
	ⓕ x1


2





**x2**


	ⓓ x8
	ⓔ x1



3




	ⓓ × 4
	ⓔ × 1



4




	ⓑ × 4
	ⓕ × 1



5




	(B) x4
	(F) x1



6




	(C) x2
	(F) x1



7





	(C) x2
	(F) x1



8






	(A) x4
	(F) x1


9



	(B) x2
	(F) x1

11



	(H) x6
---	--------