







JANINA L




1




2




3




4



5




6





1	1x	2/3
2	1x	2/3
3	1x	1/3
4	1x	1/3
5	3x	3/3
6	5x	3/3





3/3

A M8*18

 22X

B M8*35

 14X


C M8*45

 5X


D Ø18*Ø8*1.5

 41X

E M4*20

 12X

F


 6X




G

 2X

H 5mm

 1X


I.






1.



E	M4*20
	12X
F	
	6X
	100%


2.








B	M8*35
	4X
D	Ø18*Ø8*1.5
	4X
G	
	2X
H	5mm
	1X
	100%





II.


3.



A	M8*18
	
	12X
D	Ø18*Ø8*1.5
	
	12X
H	5mm
	
	1X
	





A	M8*18
	
	10X
D	Ø18*Ø8*1.5
	
	10X
H	5mm
	
	1X
	





III.

5.




- C M8*45
5X
- D Ø18*Ø8*1.5
5X
- H 5mm
1X
- 75%

6.



- B M8*35
10X
- D Ø18*Ø8*1.5
10X
- H 5mm
1X
- 75%

7.



- H 5mm
1X
- 100%



Séparez les éléments avant de trier