

SOLVEI
8141/2503
2501/8142

D MONTAGEANLEITUNG
BEDIENUNGSANLEITUNG

NL HANDLEIDING VOOR DE MONTAGE
GEBRUIKSAANWIJZING

TR MONTAJ TALIMATI
KULLANIM KLAVUZU

RO INSTRUCȚIUNI DE INSTALARE
INSTRUCȚIUNI DE UTILIZARE

FR NOTICE DE MONTAGE
MANUEL INSTRUCTIONS

HU KÖZGYŰLÉS UTASÍTÁSOK
KEZELÉSI UTASÍTÁS

SI NAVODILA ZA MONTAŽO
NAVODILA ZA UPORABO

ES INSTRUCCIONES DE MONTAJE
MANUAL DEL USUARIO

GB ASSEMBLY INSTRUCTIONS
INSTRUCTION MANUAL

PL INSTRUKCJA MONTAŻU
INSTRUKCJA OBSŁUGI

RU ИНСТРУКЦИЯ ПО МОНТАЖУ
ИНСТРУКЦИЯ ПО ЭКСПЛУАТАЦИИ

IT ISTRUZIONI DI MONTAGGIO
MANUALE DI ISTRUZIONI

SK MONTÁŽNY NÁVOD
NÁVOD NA POUŽITIE


CZ MONTÁŽNÍ NÁVOD
NÁVOD K POUŽITÍ

PT INSTRUÇÕES DE MONTAGEM
MANUAL DO USUÁRIO





HR UPUTE ZA MONTAŽU
UPUTE ZA UPOTREBU




190801




0064














R











L
















i L-5  X1	s H-90  X7	q M8*80  X7	g H-90  X2	x Fi-50  X7	[mm]
---	--	---	--	---	------





i L-5	s H-90	q M8*80	g H-90	x Fi-50
				
X1	X5	X5	X2	X5



i L-5	s H-90	q M8*20	x Fi-50
			
X1	X2	X2	X2








Service · Dienstverlening · Servis · Servis · Сервисная служба · Serviciu · Services · Servizio
 · Servisný list · Szolgáltatás · Servisní list

Name · Naam · Nazwa · Ísim · Название · Nume · Nome · Názov · Názov ·
 Název · Neve

SOLVEI



Typ · Type · Tip · Тип · Tipo · Típus



R

L

0
10
20
30
40
50
60
70
80
90
100
110
120
130
140
150
160
170
180
190
200



s H- 90 	q M8*80 	g H- 90 	x Fi- 50 [mm]
--------------------	--------------------	--------------------	--------------------------

