


---
























# ASSEMBLY INSTRUCTIONS







# ASSEMBLY INSTRUCTIONS


## PARTS LIST

 <p><b>A<sub>1</sub></b></p> <p>1PCS</p>	 <p><b>A<sub>2</sub></b></p> <p>1PCS</p>	 <p><b>B<sub>1</sub></b></p> <p>1PCS</p>	 <p><b>B<sub>2</sub></b></p> <p>1PCS</p>	 <p><b>C<sub>1</sub></b></p> <p>1PCS</p>
 <p><b>C<sub>2</sub></b></p> <p>1PCS</p>	 <p><b>C<sub>3</sub></b></p> <p>1PCS</p>	 <p><b>D</b></p> <p>2PCS</p>	 <p><b>E<sub>1</sub></b></p> <p>1PCS</p>	 <p><b>E<sub>2</sub></b></p> <p>1PCS</p>
 <p><b>F</b></p> <p>2PCS</p>	 <p><b>G</b></p> <p>1PCS</p>	 <p><b>H</b></p> <p>1PCS</p>	 <p><b>I</b></p> <p>24PCS</p>	 <p><b>J</b></p> <p>48PCS</p>
 <p><b>K</b></p> <p>4PCS</p>	 <p><b>L</b></p> <p>10PCS</p>	 <p><b>M</b></p> <p>2PCS</p>	 <p><b>N</b></p> <p>4PCS</p>	 <p><b>1</b></p> <p>M8*40</p> <p>34PCS</p>
 <p><b>2</b></p> <p>M8*18</p> <p>12PCS</p>	 <p><b>3</b></p> <p>M6*10</p> <p>16PCS</p>	 <p><b>4</b></p> <p>4*80</p> <p>1PCS</p>		


# ASSEMBLY INSTRUCTIONS





3




4



5




6





# ASSEMBLY INSTRUCTIONS


7





8



9



10





Finish

