
















Beistelltisch Glisal Montageanleitung Instruction manual



VCM Morgenthaler GmbH
D-79346 Endingen am Kaiserstuhl
service@vcm-gruppe.de
www.vcm-gruppe.de


1  x2	2  x3	3  x1
4  x2	5  x3	6  x1
7  x2	8  x3	9  x1


A	x18	B	x12	C	x1
 M6x25		 M6x22			

01

This position should use long silver screws

X3





A	x18
	
M6x25	

02

This position should use short black screws

X3



B	x12
	
M6x22	

03

