





F.4562-41

Platnost / Stand : 24.11.2023

ASSEMBLY INSTRUCTIONS - AUFBAUANLEITUNG
- INSTRUKCJA MONTAZU - MONTÁŽNÍ NÁVOD














Service • Assistenza • Dienstverlening • Serwis •
 Servis • Szerviz • Сервисная служба




Name • Nom • Nome • Naam •
 Nazwa • Jméno • Názov • Név •
 Denumire • Ísim • Название

Nr. • No. • N° • Номер • Č. • Sz


Tур • Type • Tip • Típus • Tipo •
 Тип




<p>A</p>  <p>8x</p>	<p>B</p>  <p>4x40 6x</p>	<p>C</p>  <p>4x30 4x</p>	<p>D</p>  <p>4x12 2x</p>	<p>E</p>  <p>M6x65 8x</p>	<p>F</p>  <p>8x40 26x</p>
<p>G</p>  <p>6/20 2x</p>	<p>H</p>  <p>1x</p>				



4




5




6

4x




7


2x




8




9



10







11




3218

3219

F.3265 - Milan



60 min.





Service • Assistenza • Dienstverlening • Serwis •
 Servis • Szerviz • Сервисная служба


Name • Nom • Nome • Naam •
 Nazwa • Jméno • Názov • Név •
 Denumire • Ísím • Название

Nr. • No. • N° • Номер • Č. • Sz


Тур • Туре • Tip • Típus • Tipo •
 Тип


















3218




3219






3 2x





4



5


3218

3219




6

3218




3219




7

3218




3219



8

3218



3219

